

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023998**Date Inspected:** 21-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** An Qing Xiang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector, Anand Upadhye was present during the times noted above for observations relative to the work being performed.

NDT

Outside Yard – OBG Trial Assembly

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted notification number 09197.

Magnetic Particle Testing (MT).

This QA inspector performed MT of approximately 15 % of the area previously tested and accepted by ZPMC Quality control personnel. This QA inspector generated MT report for this date. The members are identified as OBG Components. The weld designations reviewed are as follows:

SEG3013H-024.

WELDING

This QA Inspector observed the following work in progress:

Outside Yard – OBG Trial Assembly

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed ZPMC qualified welding personnel identified as 068596 perform welding by Shielded Metal Arc Welding (SMAW), on Floor beam to Sub Assembly weld at panel point 128.7 of OBG Segment 14W. Weld joint is identified as SEG3020B-116. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2212-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 040655 perform welding by Shielded Metal Arc Welding (SMAW), on Deck panel to Edge plate weld between panel points 128 and 128.3 of OBG Segment 14W. Weld joint is identified as SEG3020-017. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2212-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 067765 perform welding by Shielded Metal Arc Welding (SMAW), on Floor beam I Rib stiffener to Anchor plate weld at panel point 127 of OBG Segment 14W. Weld joint is identified as SEG3020AQ-015. ZPMC Quality Control (QC) Inspector identified as Zhu Lin was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2214-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 066751 perform welding by Shielded Metal Arc Welding (SMAW), on Floor beam I Rib stiffener weld at panel point 127 of OBG Segment 14W. Weld joint is identified as SEG3020M-007. ZPMC Quality Control (QC) Inspector identified as An Qing Xiang was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2114-FCM-1.

This QA Inspector observed ZPMC qualified welding personnel identified as 050038 perform welding by Shielded Metal Arc Welding (SMAW), on Floor beam I Rib stiffener to Anchor plate weld at panel point 127 of OBG Segment 14W. Weld joint is identified as SEG3020AP-040. ZPMC Quality Control (QC) Inspector identified as An Qing Xiang was present to monitor the welding process. The welding variables recorded by ZPMC QC appeared to be in general compliance with WPS-B-P-2214-Tc-U4b-FCM-1.

This QA Inspector observed ZPMC qualified NDT personnel perform Ultrasonic Testing on Sub Assembly part SA3416A and SA3416 C to Floor beam weld at panel point 128.3 of OBG Segment 14W. Weld joint is identified as SEG3020AV-006, 011. A Total of 16 Class A indications were found on the weld joints SEG3020AV-006, 011. See attached picture.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, phone: 15000422372 , who represents the Office of Structural Materials for your project.

Inspected By:	Upadhye, Anand	Quality Assurance Inspector
Reviewed By:	Clifford, William	QA Reviewer
